

Urgent Field Safety Notice

Advice regarding the continued safe use of
Impella Heart Pumps

Aachen, September 20, 2018

Dear Valued Customer,

This letter is to notify you about additional information for continued safe use of Impella heart pumps in patients with Medtronic CoreValve™ or Evolut™ R transcatheter aortic valve prostheses.

Affected devices:

This information concerns the following Impella heart pumps:

Impella 2.5[®]


Impella CP[®]

Description of the problem:

There is a potential risk for unintentional interaction of the Impella motor housing with the distal stent of a Medtronic CoreValve or Evolut R transcatheter aortic valves resulting in destruction of the impeller blades. This has resulted in low flow from the damaged Impella system.

The outflow struts of the CoreValve or Evolut R nitinol frame can enter the outlet opening of Impella and damage the impeller (see figure below). This interaction while running the pump can result in fracture of the impeller material. Although no events have been identified, systemic embolization of the fractured impeller material is a possibility.

This risk of interaction is increased for oversized or underexpanded frames with the distal ends not flush with the aortic wall, resulting in the distal stent structures oriented in such a way as to enter the outflow window and allow contact of the end of the stent with the spinning impeller.



Furthermore, we cannot exclude that similar interaction may also occur with transcatheter aortic valve prosthesis distributed by other manufactures, e.g. Abbott Portico™ or Boston Scientific Acurate neo™. So far, we have not been notified of clinical incidents with any of these models.

Recommendations:

Clinicians are cautioned to position the Impella system carefully in patients with transcatheter aortic valve prostheses, in particular the Medtronic CoreValve or Evolut R valves, and to be aware of this potential interaction. In this situation, clinicians should avoid repositioning while the device is running and should turn the device to P0 during repositioning or any movement that could bring the outlet windows into proximity to the valve stent structures.

If there is low flow observed in a patient implanted with a transcatheter aortic valve prosthesis while on Impella heart pump support, you should consider damage of the Impeller and replace the Impella pump as soon as possible.



Pass on this information:

This **Field Safety Notice** needs to be passed on all Impella heart pump users and those who need to be aware within your organization. In case you have passed Impella products to third parties, please make sure to forward this information to any organization where the potentially affected devices have been transferred.

Please maintain awareness on this notice and resulting action for an appropriate period to ensure effectiveness of the corrective action. (if appropriate)

This Field Safety Notice has been notified the appropriate Competent Authorities and Regulatory Agencies.

Contact reference person:

For further questions please contact:

Max Eisen: +49 (0) 241 8860-226 meisen@abiomed.com

Karsten Wallbrück: +49 (0) 241 8860-114 kwallbrueck@abiomed.com

Kind Regards

Abiomed Europe GmbH

