Welch Allyn Australia

ABN 84 062 931 462

The Metro Centre, Unit 5, 38-46 South Street

Rydalmere NSW 2116 Australia

PO Box 132 Rydalmere NSW 1701 Australia

Telephone: +61 2 9638 3000 Fax: +61 2 9638 3500



October 9, 2013

Dear Welch Allyn Propag Encore and Propag CS User,

Propag Encore Patient Monitor

Please be advised that the Propaq Encore Monitor has been obsoleted and is no longer available for purchase.

Welch Allyn will continue to provide service and support (parts and accessories) for a minimum period of 5 years (or while parts and accessories are still available from our suppliers) to enable continued use of these devices.

Propag CS Patient Monitor

The Propaq CS Monitor is no longer available to be purchased with either Mainstream or Dual stream CO₂ capability effective immediately. However, the Propaq CS Sidestream CO₂ option is still available and this end of life notification does not affect that option.

Mainstream CO₂ Sensors (Part No 008-0502-00) and Cables (008-0502-01) for Propag Encore and Propag CS

Due to restricted availability of the Mainstream CO₂ Accessories listed above, purchase of these units will be limited, and by way of Service Replacement only.

Note that you will not be able to purchase additional units through Welch Allyn Customer Service, but will be able to have your non-functioning units replaced via the Technical Service Department. You will be required to provide the faulty unit to the Technical Service Department and a replacement will be supplied by way of a normal Service Repair request.

Thank you for your understanding, and if you have any further questions or concerns please don't hesitate to contact either myself or your local Welch Allyn representative.

Sincerely,

David Cashion

Digital Product Manager Welch Allyn Australia

Mobile: 0400 429353

david.cashion@welchallyn.com